

Date: Monday, 07/07/2008 10:16:34 AM
 User: Julie Lecocq

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: D3446-21
Job Number	: 40263		
Estimate Number	: 10804		
P.O. Number	:	Part Number	: D344621
This Issue	: 07/07/2008	S.O. No.	:
Prsht Rev.	: NC	Drawing Number	: 08-054(-18)
First Issue	: 07/07/2008	Project Number	:
Previous Run	: 00015	Drawing Revision	:
Written By	:	Material	:
Checked & Approved By	: <u>JLD 08.7.07</u>	Due Date	: 11/07/2008
Comment	:	Qty:	5 Um: Each

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
----------------	------------------------------	----------------------

1.0	D344621	Left Buckle Harness
-----	---------	---------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 5.0000 Each(s)
 Left Buckle Harness
 Qty 5 of original B26202
 All SSP1105

2.0	QC	QUALITY CONTROL
-----	----	-----------------



Comment: QUALITY CONTROL
 Parts are quarantined to be returned to supplier for replacement.
 Parts are scrap.

3.0	QC21	FINAL INSPECTION/W/O RELEASE
-----	------	------------------------------



Comment: FINAL INSPECTION/W/O RELEASE

08/10/09 *[Signature]*

Job Completion



u 08.10.07

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries